


Agri Water Services Ltd
mark@agriwaterservices.co.nz

FAR Sensor Trial Chertsey 2025-26 - Ryegrass

Monday 13 Oct 2025



RootZone	Full	REFILL	Previous	Current	Deficit	Probe Dwu	Pdwu Date	EDWU	Date	Amount
0-30 cm	109 mm	77 mm	97 mm	88 mm	21 mm	1.3 mm/day	22 Oct	1.3 mm/day	22 10 0:28	32 mm